

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1 BRS	L2	531	L1 and chip	USPAT; US-PGPPU B; EPO; JPO; DERWENT ; IBM TDB	2001/10/11 22:11			0
2 BRS	L1	636	257/738.ccls.	USPAT; US-PGPPU B; EPO; JPO; DERWENT ; IBM TDB	2001/10/11 22:25			0
3 IS&R	L3	1	("5517058").PN.	USPAT	2001/10/11 22:27			0
4 BRS	L4	93	257/795.ccls.	USPAT	2001/10/11 22:33			0
5 BRS	L5	513	257/784.ccls.	USPAT	2001/10/11 22:35			0
6 BRS	L6	326	L5 and lead	USPAT	2001/10/11 22:41			0
7 BRS	L7	319	257/785.ccls.	USPAT	2001/10/11 22:50			0
8 IS&R	L8	0	("(elastic or poly\$) near (lead or contact)) and (circuit adj board)".PN.	USPAT	2001/10/11 22:51			0
9 BRS	L9	306	((elastic or poly\$) near (lead or contact)) and (circuit adj board)	USPAT	2001/10/11 23:02	Truncation Overflow. Return string from Server is: 5'180097'		1
10 BRS	L10	2377	((elast\$ or poly\$) near (lead or contactor conduct\$)) and ((circuit adj board) or substrate or chip)	USPAT	2001/10/11 23:24	Truncation Overflow. Return string from Server is: 5'0'0'ELA		1
11 BRS	L11	2332	L10 not L9	USPAT	2001/10/11 23:05			0
12 BRS	L12	401	257/\$ and L11	USPAT	2001/10/11 23:08	Truncation Overflow. Return string from Server is: 5'0'0'257		1
13 BRS	L13	4612	((elast\$ or poly\$) near (lead or contactor conduct\$))	USPAT	2001/10/11 23:26	Truncation Overflow. Return string from Server is: 5'0'0'ELA		1
14 BRS	L14	293	L13 and 257/\$.ccls.	USPAT	2001/10/11 23:26			0
15 BRS	L15	293	257/\$.ccls. and L13	USPAT	2001/10/11 23:27			0
16 BRS	L16	424	257/\$ and L13	USPAT	2001/10/11 23:28	Truncation Overflow. Return string from Server is: 5'0'0'257		1
17 BRS	L17	293	L15 or L14	USPAT	2001/10/11 23:28			0
18 BRS	L18	431	L15 or L16	USPAT	2001/10/11 23:28			0
19 BRS	L19	30	L18 not L12	USPAT	2001/10/11 23:29			0